



# HYUNDAI Technical Service Bulletin

Group	ENGINE ELECTRICAL
Number	05-36-008
Date	JULY, 2005
Model	2006 SONATA 3.3L


Subject  
**STARTER SHROUD HOLE ON 2006 SONATA WITH 3.3L ENGINE**

<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

**DESCRIPTION:**

2006 Sonata vehicles equipped with 3.3L V6 engines may have a slotted hole on the bottom surface of the stamped starter shroud just above the engine oil pan near the right front of the vehicle. This condition is normal and it does not affect vehicle operation. No action is required to fill the hole.

**NOTE: DO NOT ATTEMPT TO ADD A BOLT OR OTHER COMPONENT TO FILL THE HOLE.**



← FRONT OF VEHICLE