



# HYUNDAI Technical Service Bulletin

Group	ENGINE MECHANICAL
Number	06-20-002
Date	OCTOBER, 2006
Model	2006-07MY 3.3L & 3.8L AZERA, ENTOURAGE, SANTA FE, SONATA

Subject	<b>3.3L &amp; 3.8L TIMING CHAIN TENSIONER - PART UPDATE</b>
---------	---

<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER


## DESCRIPTION:

An updated timing chain tensioner is now available. This part may help reduce timing chain noise that may affect some vehicles during the initial 10 seconds of operation after prolonged storage.

## VEHICLES AFFECTED:

- Model:
  - 2006-07 Azera 3.8L - Produced through July 4, 2006
  - 2007 Entourage 3.8L - Produced through June 26, 2006
  - 2007 Santa Fe 3.3L - Produced through August 4, 2006
  - 2006-07 Sonata 3.3L - Produced through August 4, 2006

## PARTS INFORMATION:

PART NAME	PART IMAGE	PART NUMBER	
		PREVIOUS	NEW
Tensioner Assy - Timing Chain		24410-3C100 24410-3C200	24410-3C300