



HYUNDAI Technical Service Bulletin

Group	TRANSAXLE
Number	05-40-007-1
Date	JULY, 2005
Model	ALL

Subject

MANUAL TRANSAXLE GEAR LUBRICANT

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

This TSB supersedes TSB# 05-40-007 to update part number information.

DESCRIPTION:

A new 75W/85 manual transaxle gear lubricant has been adopted in production. The purpose of this bulletin is to provide the following information:

- Vehicle model, transaxle type and production release date information
- Previous and new gear lubricant part number information
- Gear lubricant interchangeability information

The TABLE below provides the application information for the new 75W/85, gear lubricant.

MODEL	TRANSAXLE TYPE	TRANSAXLE SERIAL NUMBER	PRODUCTION RELEASE DATE
ACCENT (LC)	M5AF3	200966	August 7, 2004
ELANTRA (XD)	M5BF2	478123	August 7, 2004
TUBRON (GK)	M5BF2 (2.0L-5SPD.) M5GF1 (2.7L-5SPD.) MFA60 (2.7L-6SPD.)	478123 172926 NOT AVAILABLE	August 7, 2004 January 3, 2005 August 1, 2003
SONATA (EF)	M5GF1	172926	January 3, 2005
SONATA (NF)	M5GF2	000001	September 1, 2004
SANTA FE (SM)	HTX (M5HF1)	Y04080097	August 9, 2004
TUCSON (JM)	M5GF1	172926	January 3, 2005

PARTS INFORMATION:

DESCRIPTION	PREVIOUS	NEW
Specification	Hyundai Genuine 75W/90	Hyundai Genuine 75W/85
Part Number	08950-00010-A	08950-00020-A

INTERCHANGEABILITY:

Code A, Previous  NEW

NOTE: Mixing of new and previous fluids in a small quantity (less than 20%) such as topping off a manual transaxle is acceptable. For all other conditions, drain previous fluid completely when filling with new Hyundai Genuine 75W/85 fluid.