



HYUNDAI Technical Service Bulletin

Group	CHASSIS
Number	07-50-002
Date	FEBRUARY, 2007
Model	ALL

Subject
PSF-4, HYUNDAI GENUINE POWER STEERING FLUID

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

DESCRIPTION:

This bulletin provides the PSF-4, Hyundai Genuine Power Steering Fluid, part number and interchangeability information.

DESCRIPTION	PART NUMBER
PSF-4 - Hyundai Genuine Power Steering Fluid	00232-06010

INTERCHANGEABILITY:

- PSF-4 to PSF-3 —————▶ Topping off or adding up to 50% PSF-4 to a PSF-3 system is acceptable.

NOTE: Do not add more than 50% of the total system volume of PSF-4 to PSF-3. The PSF-3 fluid should be drained and replaced with PSF-4 power steering fluid.

- PSF-3 to PSF-4 —————▶ Not OK (Do not add PSF-3 to a PSF-4 system)