



HYUNDAI Technical Service Bulletin

Group	TRIM
Number	06-80-001
Date	FEBRUARY, 2006
Model	2006 TUCSON & SONATA

Subject
INSTALLATION OF TIE DOWN PLUGS DURING PDI

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

DESCRIPTION:

During the Pre Delivery Inspection (PDI) process for the 2006 MY Tucson and Sonata vehicles, the tie down holes must be covered to prevent water leaks into the vehicle.



A set of plugs is being supplied in the vehicle's glove box. The plugs are to be installed to the tie down holes during normal PDI process.

The 2006 Tucson packet contains two rear tie down plugs. The 2006 Sonata packet contains 4 plugs, two for the front and two for the rear. The two front plugs are larger than the rear plugs.

Replacement plugs can be ordered through your facing Parts Distribution Center (PDC).



PARTS INFORMATION:

PART NUMBER	DESCRIPTION	MODEL/APPLICATION	PHOTO
84142-3K000	Plug - Front Side Member Drain	Sonata / Front Tucson / Rear	
84143-3K000	Plug - Drain	Sonata / Rear	

PROCEDURE FOR TUCSON VEHICLE:

1. Locate the tie down locations under the vehicle.





HYUNDAI Technical Service Bulletin

Group

TRIM

Number

06-80-001

2. Install the plugs to the rear tie down openings.




PROCEDURE FOR SONATA VEHICLE:

1. Locate the two front tie down locations under the vehicle.



2. Install the plugs into the front tie down openings.



3. Locate the rear tie down locations under the vehicle.
4. Install plugs to the rear tie down openings.



WARRANTY INFORMATION:

Normal PDI claim entry applies using PDI Claim Entry Screen.

The installation of the tie down plugs should be performed concurrently with the "under vehicle" damage inspection during the PDI process.